


**ISLIP  
LI MAC ARTHUR AIRPORT**

**SUFFOLK CO.  
ISP**




Runways	Coordinates
15R/33L: 5186 x 150 (ASPH-G)	Latitude 40-47-42.90000N
15L/33R: 3175 x 75 (ASPH-G)	Longitude 073-06-00.80000W
10/28: 5034 x 150 (ASPH-F)	H1: 50 x 50 (ASPH-G)
06/24: 7006 x 150 (ASPH-E)	H2: 50 x 50 (ASPH-G)

Communications	Navigation
ASOS (631) 471-0690	Elevation 215
ATIS 120.725	NM from City 02 E
UNICOM 122.95	Instr Appr. PRECISION
CTAF 119.3	
CLNC 121.85	
GROUND 135.3	
TOWER 119.3 124.3 (1100-0400Z)	
APP/DEP 118.0 (NEW YORK)	NY RCO 122.2, 122.6 (NY RADIO)
AIRSPACE: CLASS C 1100-0400Z, CTC APP CON 118.0 (330° - 179°), OTHER TIMES CLASS E	

**ISLIP  
LI MAC ARTHUR AIRPORT**

**SUFFOLK CO.  
ISP**



Owner/Manager		Services	
Owner:	Town of Islip	Fuel	100LL/JETA
Manager:	Ms. Teresa A. Rizzuto 100 Arrival Avenue Ronkonkoma, NY 11779-7398	Airframe Repairs	MAJOR
		Engine	MAJOR
		Attended	ALL/ALL/ALL
		Airline Airport	YES
Phone	(631) 467-3300		
Fax	(631) 467-3348		
E-mail:	Commissioner-at@townofislip-ny.gov		
Web site:	www.macarthurairport.com		

FBO	Remarks
Garrett Aviation Services (631) 585-4700 (800) 468-4480 Freq 131.65	BIRD ACTVY ON & INVOF ARPT. ADZY: TFC LNDG RWY 33L HIGH DENSITY VFR TFC OPERG 600' MSL & BELOW VCNTY BAYPORT AERODROME 3 MILES SE. WHEN ATCT CLSD ACTVT MRL RY 15R/33L; TWY LGTS - CTAF. HIRL RY 06/24 PRESET LOW INTST; TO INCR INTST ACTVT - CTAF; MALSR RY 06 OR RY 24 PRESET MED INTST FOR PREVAILING WIND RY. RYS 15L/33R & 10/28 CLSD TO FIXED WING ACFT AT NGT & AVBL FOR TXG. FOR ADD'L ARPT INFO GO TO: <a href="http://www.gcr1.com/5010web/">http://www.gcr1.com/5010web/</a>
NY Jet/Mid Island Air Service (631) 588-5400 Freq 123.5	
Long Island Jet Center (631) 588-0303 Freq 129.77 (877) FLY-2-ISP	