


**SARANAC LAKE
ADIRONDACK REGIONAL AIRPORT**

**FRANKLIN CO.
SLK**



Runways

05/23: 6573 x 150 (ASPH-G)
09/27: 3998 x 100 (ASPH-F)

Coordinates

Latitude 44-23-07.1000N
Longitude 74-12-22.3000W

Communications


ASOS 124.175 (518) 891-6696
CTAF/U 123.0
APP/DEP 120.35 (BOSTON)
PCL 123.0

Navigation

Elevation 1663
NM from City 4 NW
Instr Approach PRECISION

**SARANAC LAKE
ADIRONDACK REGIONAL AIRPORT**

**FRANKLIN CO.
SLK**



Owner/Manager

Owner: Town of Harrietstown
Manager: Mr. Ross Dubarry
96 Airport Road
Saranac Lake, NY 12983

Services

Fuel JET A, 100LL
Airframe Repairs NONE
Engine MINOR
Attended ALL/ALL/0600-2100
Airline Airport YES
Transportation RENTAL CAR, LIMO
Food ON FIELD

Phone: (518) 891-4600 x 106

Fax: (518) 891-0870

E-mail: airportmanager@harrietstown.org

Web site: www.harrietstown.org/

FBO

Adirondack Regional FBO
(518) 891-4600 Freq. 123.0

Remarks

FOR ARPT ATTENDANT AFTER HRS CALL 518-891-2256/8510. PPR 48 HR FOR UNSKED ACR OPNS WITH MORE THAN 30 PSGR SEATS CALL AMGR ACTVT HIRL RY 05/23, MIRL RY 09/27, MALSR RY 23, PAPI RY 05, & TWY LGTS - CTAF. TWY B UNAVBL TO ACFT WITH WINGSPAN 79 FT & ABV. FOR ADD'L ARPT INFO GO TO: <http://www.gcr1.com/5010web/>