

BUFFALO
BUFFALO NIAGARA INTERNATIONAL AIRPORT

ERIE CO.
BUF




| Runways | | Coordinates | |
|---------|---------------------|-------------|-----------------|
| 14/32: | 7161 x 150 (ASPH-G) | Latitude | 42-56-25.8890N |
| 05/23: | 8827 x 150 (ASPH-G) | Longitude | 078-43-55.8000W |

| Communications | | Navigation | |
|----------------|-----------------------|----------------|-----------|
| ATIS | 135.35 (716) 635-0532 | Elevation | 728 |
| CLNC | 124.7 | NM from City | 05 E |
| GROUND | 121.9 | Instr Approach | PRECISION |
| TOWER | 120.5 | | |
| APP/DEP | 126.15 (BUFFALO) | | |

BUFFALO
BUFFALO NIAGARA INTERNATIONAL AIRPORT

ERIE CO.
BUF



TAXI DIAGRAM

| Owner/Manager | | Services | |
|---------------|--------------------------|------------------|-------------|
| Owner | Niagara Frontier Trans. | Fuel | JETA 100LL |
| Manager | Mr William Vanecek | Airframe Repairs | MAJOR |
| | 4200 Genesee Street | Engine | MAJOR |
| | Buffalo NY 14225 | Attended | ALL/ALL/ALL |
| Phone | (716) 630-6000 | Airline Airport | YES |
| Fax | (716) 630-6070 | Transportation | |
| E-mail | william_vanecek@nfta.com | Food | |
| Web site | www.nfta.com/airport | Lodging | |

| FBO | Remarks |
|--|---|
| Prior Aviation Service (716) 633-1000 Freq. 131.75 | RWY 05 HEAVY CONCENTRATION OF GULLS; BLACKBIRDS & STARLINGS UP TO 5000 FT ON & INVOF ARPT. DEER ON & INVOF ARPT. FOR FBO SVCS CTC 131.75; FOR CARGO SVCS CTC 122.95. TWY 'A' SOUTHWEST RUNUP AREA/HOLDING BAY MARKED DESIGN GROUP 3 ACFT (GENERALLY B727 OR SMALLER) UNAVAILABLE DESIGN GROUP 4 (INCLUDES BUT NOT LIMITED TO B757 DC8). TWY 'K1' CLSD 2100-0600 DAILY. FOR ADD'L ARPT INFO GO TO: http://www.gcr1.com/5010web/ |