

NEWBURGH  
STEWART INTERNATIONAL AIRPORT

ORANGE CO.  
SWF




Runways	Coordinates
16/34: 6004 x 150 (ASPH-G)	Latitude 41-30-14.8000N
09/27: 11817 x 150 (ASPH-G)	Longitude 074-06-17.4000W
H1: 40 x 40 (ASPH-G)	

Communications	Navigation
ATIS 124.575 (845) 567-9311	Elevation 491
UNICOM 122.95	NM from City 03 NW
GROUND 121.9	Instr Approach PRECISION
TOWER 121.0	
APP/DEP 132.75 (NEW YORK)	

NEWBURGH  
STEWART INTERNATIONAL AIRPORT

ORANGE CO.  
SWF



TAXI DIAGRAM

Owner/Manager	Services
Owner: PA NY & NJ	Fuel JETA 100LL
Manager: Ms. Diannae Ehler	Airframe Repairs MAJOR
1180 First Street	Engine MAJOR
Bldg 138	Attended ALL/ALL/ALL
New Windsor, NY 12553	Airline Airport YES
	Transportation TAXI, LIMO, COURTESY VAN, BUS SERVICE TO BEACON (NY)
Phone: (845) 564-7200	Lodging OFF - 3 MILES
Fax: (845) 567-1321	
Web site: <a href="http://www.stewartintlairport.com/airports/stewart.html">www.stewartintlairport.com/airports/stewart.html</a>	

FBO	Remarks
Atlantic Aviation (845) 567-9800	BIRDS & DEER ON & INVOF ARPT. AVOID ORANGE COUNTY ARPT LCTD 7 NM WNW DURG VFR APCHS. BE AWARE - EXTENSIVE GLIDER ACTVTY 8 MI EAST OF HUO VORTAC IN A 5-MI RADIUS. NOISE ABATEMENT PROCEDURES IN EFFECT CTC AMGR 914-564-7200. TWY C BTN TWY B & F NOT VISIBLE FROM TOWER. RWY 09 MID-POINT AND ROLLOUT RVR OTS INDEFLY. RWY 09 SEQUENCE FLASHERS OTS INDEFLY. TWY L, M, N EDGE LIGHTS OTS INDEFLY. FOR ADD'L ARPT INFO GO TO: <a href="http://www.gcr1.com/5010web/">http://www.gcr1.com/5010web/</a>
Richmor Aviation (845) 567-2601	